

Download 2011 Ford Fusion Service Repair Manual Software

The 2011 Ford Fusion has 86 problems reported for power steering failure. Average repair cost is \$1,620 at 72,150 miles. (Page 1 of 5) Ford Motor Company (Ford) is recalling certain all weather driver side accessory floor mats sold for use in model year 2006-2011 Ford Fusion and Mercury Milan, 2006 Lincoln Zephyr, and 2007-2011 ...2010-2012 Fusion, 2010-2011 Milan – Manual Temperature Control Equipped – A/C Will Blow Warm Intermittently – Intermittent Poor A/C Performance. Some 2010-2012 Fusion and 2010-2011 Milan vehicles equipped with manual temperature control may experience the climate control system intermittently blowing warm air when cold air is selected or the a/c is turned on. Find 2013 Ford Fusion recalls information, reported by the NHTSA, and we will help you find a nearby service center where you can get your car fixed.