

Download 94 Escort Sensor Manual

Where is the transmission speed sensor located in a 94 escort lx? Could this be responsible for erratic auto - Answered by a verified Ford Mechanic. ... I have a 1999 Ford Escort LX, manual transmission, and was wondering what could be causing my speedometer to suddenly "die".94 ford escort: replace the 5 speed manual transmission..trip I need to replace the 5 speed manual transmission in my 94 ford escort. Have a lead on a 98 escort trans in a distant city but need to know before making the trip if this 98 trans will work in my 94.Ford Escort 1.9L 1994, Water Temperature Sensor by Santech®. Increase the life of your vehicle's engine by keeping your cooling system in top condition. Replace your faulty engine cooling component with this highly efficient replacement...I have a 94 escort that has no spark, I have changed the ignition module the coil pack and crank sensor. There is a signal at the crank sensor but doesnt seem to be getting to eec.